

REFERENCES

Refurbishment of fuel storage tanks

Project Customer	Capacity	Year of Construction	Scope of work
Air Base Incirlik, Turkey Cegelec AT GmbH & Co. KG Frankfurt, Germany	1 x 2.000 m ³ UST	2006	New concrete bottom New shotcrete wall tba leak protection lining
Aviano, Italy AMEC Earth & Environmental USA	4 x 1.250 m ³ 1 x 750 m ³ UST	2008	Tank inspection Welding repair Patch plates Mechanical repair Coating repair Complete coating of 2 tanks
Tank Storage Arahall, Spain Compañía Logística de Hidrocarburos CLH, S. A. Madrid, Spain	1 x 12.700 m ³ UST	2010	Welding repair Patch plates Mechanical repair New concrete bottom New shotcrete wall tba leak protection lining Coating of tank roof
OMV Tank Storage Vidin, Bulgaria TFR Tank Farm Revamp GmbH Graz, Austria	4 x 500 m ³ 1 x 700 m ³ 2 x 2000 m ³ AST	2009	Tank bottom inspection Ultra-sonic thickness test tba leak protection lining at tank bottoms
Castelsarrasin, France Ministère de la défense Etablissement Administratif et Technique du Service des Essences des Armées Nancy, France	4 x 3.750 m ³ UST	under construction	New concrete bottom New shotcrete wall tba leak protection lining double-skin system with leak detection Coating of tank roof
	3 x 100 m ³ 3 x 30 m ³ UST	under construction	Blasting works Coating of tanks
Heavy Fuel Tank Compagnie de chauffage Grenoble, France	1 x 650 m ³	2010	Concrete repair tba leak protection lining double-skin system with leak detection Coating of tank roof

AST = Above ground storage tanks
 UST = Underground storage tanks

Last up date:
 10/2010